

Date : 2/27/2009

Patent No. : 7,025,448 B2 Serial No. : 10/665,752

Inventor(s) : Olsen

Issue Date : April 11, 2006

Title : FLUID INTERCONNECT IN A REPLACEABLE INK RESERVOIR

FOR PIGMENTED INK

Doc./File No. : 10001896-5

Re: Certificate of Correction

Consideration has been given your request for a certificate of correction, for the above-identified patent under the provisions of Rule 1.322 and 1.323.

Respecting the alleged error(s) in your request, in column 10, line 47-49, of claim 5, the printed patent is/are printed in accordance with the amendment of claim 12, now claim 5, dated 6/7/04, and does not reflect the changes that are requested in item two of the 1050/SB-44 or in any other amendment. Not correction is in order here.

In view of the foregoing, your request in this matter is denied.

A certificate of correction will issue to correct the remaining errors noted in your request.

However, further consideration will be given your request upon receipt of of a request for <u>Reconsieration</u> (w/supporting documentation) in this matter upon receipt of a copy of the 1449 or 892 with the requested reference(s) considered by the Examiner.

Ernest C. White, *LIE* (703) 308-9390 x122 Mary F. Diggs, *Supervisor* (703) 308-9390 x125 Decisions & Certificates of Correction Branch

HEWLETT-PACKARD COMPANY Intellectual Property Administration P. O. Box 272400 Fort Collins CO 80527-2400